



Due to low demand and the high cost of maintaining it as a separate product, PCB Assembly 402042 is no longer manufactured.

In all cases, it can be replaced by  
PCB Assembly 402239  
which is a fully populated version (8 array switches) and includes  
an RS485 port by default.

For full details, refer to datasheet:

<https://micha.co.uk/pdf/402239-DS.pdf>